

POPPLETON HISTORIC STUDY

B-2751

MAG-1#0427515404

Block 252 Lot 65-61 Address 103-111 S. Schroeder Street

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

Rating

Architectural

Condition

A	Significant-save	good	fair	poor	bad	
B	Quality-Indiv./groups-save	good	fair	poor	bad	109
C	Important to street/groups	good	fair	poor	bad	
D	Insignificant/detrimental	good	fair	poor	bad	

Notable features:



Number 109 is in good repair with well-kept garden beside it on lot 61. These are small workers' houses, late in date despite the gable roofs. Condition is various; should be rehabilitated. Numbers 103, 105 and 107 are formstoned.

Environmental context:


Number 103 is vacant and derelict. One large street tree should be fed and larger new ones put in.



Sanborn Maps



B-2751
103-111 S. Schroeder Street (111 demolished)
Block 0252, Lots 061-065
Baltimore City
Baltimore West Quad



GIS data Courtesy of
the City of Baltimore, MOIT/EGIS

